### UNCLASSIFIED

### AD NUMBER

AD367499

# **CLASSIFICATION CHANGES**

TO: unclassified

FROM: confidential

# **LIMITATION CHANGES**

#### TO:

Approved for public release, distribution unlimited


#### FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

# AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

### THIS PAGE IS UNCLASSIFIED





#### Enclosure (D)

Subject: Bureau of Ordnance Material Group Final Report for Tests "A" & "B".

Classification (Geneelled) (Changed to CONFIDENTIAL by Authority of Joint Chiefs OF Staff JCS 1795/36 DATED 15 APRIL 1949 By John Culley Waj Africap Date JUN 281949

#### PART X - PHOTOGRAPHIC APPENDIX

(a)	General Explosives	Volume :	
(c)	Guns & Hounts Underwater Ordnance	Volume :	
(e)	Armor & Metallurgy	Volume	
71	Fire Control	Volume '	<b>Y</b>

(f) Fire Controlv Volume V

(g) Aviation Ordnance Volume V


U. S. GOVERNMENT ACCEMENT MAY COMES OF THIS MEPORY DIRECTLY

FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

Director

Director

Defense Atomic Support Agency
Washington, D. C. 20301



**CONFIDENTIAL** 

Inclosure (u)

GROUP-3 JAN 1535

Downgraded at 12 jear intervals;

Not automatically declaration.

Inclosure (D) to Director Ship Material Serial 001500.

Page 1 of 249 pages. Volume III

4214

C

#### S-E-C-R-E-T

### GENERAL PHOTOGRAPHIC INDEX

### TESTS "A" AND "B"

		PAGE
	U.S.S. ARKANSAS (EB-33)	
AACR92-1774-11	General Damage.	3
	U.S.S. NEVADA (EB-36)	
AACR68-1746-11	General Damage.	4
	U.S.S. PENSACOLA (CA-24)	
AACR98-1965-9 AACR98-1967-7	Effect of secondary fires abreast Turret 4. General Damage.	5 6
	U.S.S. RHIND (DD-404)	
AACR92-1771-2	Torpedoes protruding from tubes.	7


# S-I-C-R-I-I



IFIDENTIAL


U.S.S. ARKANSAS (FB-33) - After Able Showing general damage.
Photo. No. AA-CH-92-1774-11.





U.S.S. NEVARA (BE-36) - After Able Showing general damage. Fboto. No. AA-CK-68-1726-11.


while is T collegers (i) to Director Ship Material Serial College.



U.S.S. PENSACOLA (Ca=24) - After Atle Showing effect of secondary fires obreast Turret 4. Photo. No. A -08-08-196-49.


### BECRET

Enclosure (D) to Director Ship Material certal extends.



U.S.S. PLNSACOLA (CA-24) - After Able Showing general damage. Photo. No. AA-Ck-98-1967-7.

EEELEI Enclosure (b) to Director Ship Material Serial 001500.



U.S.S. RHIND (DD-404) - After Able Showing general damage and torpedoes pretruding from the tubes. Photo. No. AA-CR-1771-2.

#### BEGRET

Enclosure (D) to Director Ship Material Serial 001500.

? Page 7 of 249 pages. Volume III.

### EXPLOSIVE PHOTOGRAPHIC INDEX

	TEST MAN & MBM	
DA-CR T2-11-11, EX	P / 2 Probable Secondary Explosion.	PAGE 17
	U.S.S. NEVADA (BB-36)	
BA-CR 92-429-6	14"/45 Smokeless Powder Stowage	18
BA-CR 92-429-12	Shell Deck Projectile Stowage	19
BA-CR 92-430-1	Test Ammunition in Position in No. 4	Turret 20
BA-CR 92-430-4	5"/38 Projectiles and SPCG, Powder	21
BA-CR 92-430-5	20 MM Ammunition Clipping Room	22
BA-CR 92-430-6	40 MM Ammunition Clipping Room	23
BA-CR 92-430-7	20 MM Ready Service Box	24
AA-CR 97-1535-7	20 MM Ready Service Box	25
AB-CR 76-1934-4	20 MM Ammunition Stowage	26
AB-CR 76-1934-5	40 MM Ammunition Stowage	27
	U.S.S. NEW YORK (BB-34)	
BA-CR 97-961-1	14"/45 Projectiles	28
BA-CR 97-961-2	5"/51 Smokeless Powder	29
BA-CR 97-961-3	5"/51 Projectiles	30
BA-CR 97-961-9	SPCG Powder in Ready Service Box	31
BA-CR 97-961-10	5"/51 Projectiles in Mount No. 6	32
BA-CR 97-961-12	3"/50 Ready Service Locker	33
BA-CR 97-962-12	14"/50 Smokeless Powder	34
BA-CR 97-971-2	Special Test Ammunition	35
BA-CR 97-971-5	Aircraft Bomb Stowage	36
AA-CR 87-2540-3	Damage to 3"/50 Ready Service	37
AA-CR 87-2540-4	3"/50 Ready Service Locker	38
	U.S.S. SARATOGA (CV-3)	
BA-CR 92-457-5	Incendiary Bomb Stowage	39
BA-CR 92-457-7	20 MM Ammunition Stowage	40
BA-CR 92-457-9	Aircraft Rocket Head Stowage	41
BA-CR 92-559-2	Aircraft Bomb in Universal Stowage	42
BA-CR 92-559-7	Aircraft Bomb Stowage	43
BA-CR 92-559-8	Aircraft Bomb Stowage	44
BA-CR 92-559-10	5"/38 Smokeless Powder Magazine	45
		<b>*</b> -

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 8 of 249 pages. Volume III.

### EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

		TEST NAW & "B"	<b>5</b> 4 05
		U.S.S. SARATOGA (CV-3) (Cont'd)	PAGE
BA-CR	92-560-2	Aerial Torpedo Stowage	46
BA-CR	92-560-4	5#/38 Handling Room	47
BA-CR	92-560-5	5#/38 Handling Room	48
-	92-560-6	Special Test Ammunition	49
	92-560-8	Special Test Ammunition	50
	92-560-10	40 MM Clipping Room	51
	63-1560-3	Aircraft Bombs	52
	63-1560-6	Aircraft Bombs	53
	63-1560-7	11"/75 Aircraft Rockets	54
	63-1560-8	11"/75 Aircraft Rockets	55
	63-1560-9	350 lb., Aerial Depth Bombs	56
	63-1560-10	350 lb., Aerial Depth Bombs	57
	63-1560-12	5"/O Aircraft Rockets	58
	63-1563-1	350 lbs., Aerial Depth Bombs	59
	63-1563-4	500 lb., General Purpose Bombs	<b>6</b> 0
	63-1563-5	Aerial Torpedo, Mark 13	61
	63-1563-6	5"/O Aircraft Rockets	62
BA-CR	63-1563-7	11"/75 Aircraft Rockets	63
		U.S.S. INDEPENDENCE (CVI-22)	
BA-CR	63-320-2	1000 lb., Armor Piercing Bomb	64
	63-320-5	50 Caliber Stowage	65
	63-320-7	40 MM Ammunition Magazine	66
	63-320-11	Aerial Torpedo Stowage	67
	92-414-5	40 MM Ammunition Magazine	68
	92-414-6	Bomb Fuze and Detonator Stowage	69
	92-414-8	Aircraft Rocket Motor Magazine Stowage	70
	92-414-10	260 lb., Fragmentation, Aircraft Bombs	71
	92-429-5	40 WM Ammunition Clippi ; Room	72
		U.S.S. PENSACOLA (CA-24)	
BA-CR	15-12	20 MM Ammunition Clipping Room	73
	81-315-4	5"/25 Smokeless Powder Magazine	74
	81-315-6	5"/25 Smokeless Powder Magazine	75
_	81-315-10	34/55 Smokeless Powder Magazine	76
	81-315-11	8#/55 Smokeless Powder Magazine	77
_			

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 9 of 249 pages. Volume III.

# EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B" (Cont'd) U.S.S. PENSACOLA (CA-24) (Cont'd)	PAGE
BA-CR 81-316-1	40 MM Ammunition Ready Service Stowage	78
BA-CR 92-323-5	8"/55 Smokeless Powder Magazines	79
BA-CR 92-323-9	40 MM Ammunition Magazine	80
BA-CR 92-323-10	5 <sup>m</sup> /25 Ready Service Locker	81
BA-CR 92-323-11	5 <sup>m</sup> /25 Ready Service Locker	82
BA-CR 92-324-1	Projectile Stowage on the Shell Deck	83
BA-CR 92-324-2	Special Test Ammunition No. 3 Turret	84
BA-CR 92-324-3	Special Test Ammunition No. 4 Turret	85
AA-CR 92-1778-2 AA-CR 92-1778-3 AA-CR 92-1778-4	Turret No. 4 Turret No. 4 Special Test Ammunition in Turret No.	86 87
AA-CR 92-1778-5 AA-CR 87-2539-7	20 MM Loaded Magazines 5"/25 Ready Service Locker	4 00 89 90
AB-CR 80-1618-12	8"/55 Projectile	91
AB-CR 80-1675-4	8"/55 Smokeless Powder Stowage	92
AB-CR 80-1676-1	40 MM Ammunition Stowage	93
AB-CR 80-1676-2	5"/25 Smokeless Powder Magazine	94
AB-CR 80-1676-3	8"/55 Smokeless Powder Magazine	95
AB-CR 80-1676-5	40 MM Ammunition Stowage	96
AB-CR 80-1677-12 AB-CR 80-1678-1 AB-CR 80-1678-2	8 <sup>m</sup> /55 Projectiles on Shell Deck 8 <sup>m</sup> /55 Projectiles on Shell Deck 8 <sup>m</sup> /55 Projectiles on Shell Deck	97 98
AB-CR 80-1678-6	8m/55 Projectiles on Shell Deck	99
AB-CR 100-4205-1	5m/25 Ready Service Locker	100
AB-CR 100-4205-3	40 MM Ammunition Stowage	101
200-4x0y=y		102
	U.S.S. SALT LAKE CITY (CA-25)	
BA-CR 92-901-10	5"/25 Ready Service Locker	103
AA-CR 87-2539-8	5"/25 Ready Service Locker	104
AA-CR 87-2539-9	5"/25 Ready Service Locker	105
	U.S.S. STACK (DD-406)	
BA-CR 81-415-4	Torpedo Impulse Charge Stowage	106
BA-CR 81-415-5	Depth Charge Marker Stowage	107
BA-CR 81-415-6	Depth Charge Impulse Stowage	108
BA-CR 81-415-8	Depth Charge Stowage	109
SECRLI		

Enclosure (D) to Director Ship Material Serial 001500.

Page 10 of 249 pages. Volume III.

### EXPLOSIVE PHOTOGRAPHIC INLEX (Cont'd)

		TEST "A" & "B" (Cont'd)	204.00
		U.S.S. ANDERSON (DD-411)	PACE
BA-CR	85-447-1	Depth Charge Stowage	110
		U.S.S. HUGHES (DD-410)	
BA-CR	81-486-4	20 MM keady Service Box	111
BA-CR	81-486-5	40 MM Clipping Room	112
BA-CR	81-486-6	20 MM Magazine	113
BA-CR	81-486-9	5"/38 Smokeless Powder Magazine	114
BA-CR	81-486-10	5"/38 Upper Handling Room	115
BA-CR	81-486-11	5"/38 Projectile Stowage	116
BA-CR	81-561-1	5"/38 Gun House	117
AB-CR	76-1931-1	5"/38 Upper Handling Room	118
AB-CR	76-1931-2	5 <sup>M</sup> /38 Upper Handling Room	119
AB-CR	76-1931-3	5#/38 Upper Handling Room	120
AB-CR	76-1931-4	5"/38 Upper Handling Room	121
AB-CR	76-1931-5	5"/38 Upper Handling Room	122
AB-CR	76-1931-6	5"/38 Projectile Stowage	123
AB-CR	76-1931-7	5"/38 Smokeless Powder Stowage	124
AB-CR	76-1932-3	40 MM Ammunition Stowage	125
		U.S.S. WAINWRIGHT (DD-419)	
BA-CR	81-418-4	Pyrotechnic Stowage	126
BA-CR	81-418-6	40 MM Ammunition in Bulwark Shields	127
		U.S.S. LAMSON (DD-367)	
BA-CR	81-316-11	Nepth Charges, Mark 9	128
		U.S.S. CONYNGHAM (DD-371)	
	92-289-1	Special Test 5"/38 Projectiles	129
BA-CR	92-289-2	5#/38 Powder Ready Service	130
		U.S.S. RHIND (DD-404)	
BA-CR	81-314-4	5#/38 Projectiles Special Test	131

### SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 11 of 249 pages. Volume III.

### EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B" (Cont'd)	D.4.05"
	U.S.S. MUGFORD (DD-389)	PAGE
BA-CR 92-413-4	Special Test 5"/38 Projectiles	132
BA-CR 92-413-6	5"/38 Upper Handling Room	133
BA-CR 92-413-9	5*/38 Ammunition Hoist	134
BA-CR 92-414-2	5"/38 White Phosphorous Projectiles	135
	U.S.S. RALPH TALBOT (DD-390)	
BA-CR 92-325-2	Special Test 5"/38 SPCG Powder	136
BA-CR 92-325-4	Special Test 5"/38 SPCG Powder	137
	U.S.S. PRINZ EUGEN (CA-GLR)	
BA-CR 92-930-4	8 inch Powder Magazine	138
BA-CR 92-930-5	8 inch Powder Magazine	139
BA-CR 92-930-6	8 inch Projectile Magazine	140
BA-CR 92-930-7	10.5 cm Powder Stowage	141
BA-CR 92-930-8	Projectile Fuze Stowage	142
	NAGATO (Ex-Jap BB)	
BA-OR 76-131-5	350 lb., Aerial Depth Bomb	143
BA-CR 76-131-8	Aerial Torpedo Warhead, Mark 13	144
BA-CR 76-131-10	350 lb., Aerial Depth Bomb	145
BA-CR 76-131-11	Aerial Torpedo Warhead, Mark 13	146
BA-CR 76-131-12	500 lb., Aircraft Bomb	147
BA-CR 60-917-1	40 cm Armor Piercing Projectiles	148
BA-CR 60-917-5	25 MM Ammunition Stowage	149
BA-CR 60-917-6	40 cm Common Projectile Stowage	150
BA-CR 76-1799-1	5"/O Aircraft Rocket Heads	151
AA-CR 87-2539-2	350 lb., Aeriel Depth Bomb	152
AA-CR 87-2539-3	Damaged Sister Hook	153
AA-CR 87-2539-4	350 lb., Aerial Depth Bomb	154
AA-CR 87-2539-5	500 lb., Aircraft Bomb	155
AA-CR 87-2539-6	Jet Assisted Take-Off Unit	156
	U.S.S. PILOTFISH (SS-386)	
BA-CR 97-962-4	40 MM Ammunition Ready Service Locker	157
BA-CR 97-962-9	Pyrotechnic Stowage	158
SECRET		
Englamma (D) to Die	menton Chin Metomial Semial (101501).	

### EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B" (Cont'd)	D.C.C
	U.S.S. SKATE (SS-305)	PAGE
BA-CR 63-946-1	5 inch Smokeless Powder Stowage	159
BA-CR 63-946-2	5 inch Ready Service Locker	160
AA-CH 92-1778-7	40 MM Ammunition Ready Service Locker	161
AA-CR 92-1778-8	40 MM Ammunition Ready Service Locker	162
AA-CR 92-1778-9	5 inch Ready Service Locker	163
	U.S.S. SEARAVEN (SS-196)	
BA-CR 97-589-5 BA-CR 97-589-6	4"/50 Ready Service Locker 4"/50 Ready Service Locker	164
		165
BA-CR 97-589-10	Small Arms Ammunition Stowage	166
BA-CR 97-589-11	Small Arms Ready Service Locker	167
BA-CR 97-589-12	4"/50 Smokeless Powder Stowage	168
BA-CR 97-962-2	Demolition Charge, Mark 2	169
	U.S.S. CARLISLE (APA-69)	
BA-CR 93-96-11	500 lb., Aircraft Bomb	170
BA-CR 93-96-12	350 lb., Aerial Depth Bomb	171
	U.S.S. CRITTENDEN (APA-77)	
BA-CR 81-906-2	350 lb., Aerial Depth Bomb	172
BA-CR 81-906-4	500 lb., Aircraft Bomb	173
AA-CR 60-145-4	500 lb., Aircuaft Bomb	174
AA-07. 60-145-5	500 lb., Aircraft Bomb	175
AA-LR 60-145-6	350 lb., Aerial Dapoh Bomb	176
AA-CR 60-145-7	350 lb., Aerial Depth Bomb	177
AA-CR 98-1960-1	500 lb., Aircraft Bomb	178
	U.S.S. BARROW (APA-61)	
BA-CR 93-128-1	5 inch Aircraft Rocket Heads	179
	U.S.S. BUTTE (APA-68)	
BA-CR 93-128-3	Incendiary Bomb Clusters	180

# SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 13 of 249 pages. Volume III.

# EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B" (Contid)	
		PAGE
	U.S.S. GASCONADE (APA-35)	
BA-CR 93-128-5	Incendiary Bomb Clusters	181
BA-CR 81-432-11	5#/38 Projectile Stowage	182
BA- CR 81-432-12	5#/38 Smokeless Powder Stowage	183
BA-CR 81-433-3	40 MM Ammunition Clipping Room	184
AB-CR 100-4207-1	5"/38 Projectile Stowage	185
AB-CR 100-4207-3	40 MM Ammunition Clipping Room	186
AB-CR 100-4207-4	40 MM Ammunition Magazine Stownge	187
AB-CR 100-4207-5	40 MM Amminition Magazine Stowage	188
AB-CR 100-4210-11	5"/38 Projectile Stowage	189
AB-CR 100-4210-12	5"/38 Smokeless Powder Stowage	190
	U.S.S. CATRON (APA-71)	
BA-CR 76-129-6	350 lb., Aerial Depth Bomb	191
BA-CR 76-129-7	500 lb., Aircraft Bomb	192
BA-CR 85-591-6	Jet Assisted Take-Off Unit	193
BA-CR 85-591-9	500 lb., Aircraft Bomb	194
BA-CR 85-591-10	500 lb., Aircraft Bomb	195
BA-CR 85-591-12	350 lb., Aerial Depth Bomb	196
BA-CR 85-592-1	5 inch Aircraft Rocket Heads	197
	U.S.S. BLADEN (APA-63)	
RA-CR 76-298-4	Arrangement of Aircraft Munitions	198
	U.S.S. BRISCOE (APA-65)	
BA-CR 97-422-7	5 inch Aircraft Rocket Heads	199
BA-CR 97-422-8	20 MM Ammunition Clipping Room	200
BA-CR 97-454-1	40 MM Ammunition Ready Service Stowage	201
BA-CR 97-454-5	40 MM Ammunition Magazine	202
AA-CR 92-1776-1	5 inch Aircraft Rocket Heads	203
AB-CR 97-4046-3	20 MM Magazine Ready Service Stowage	204
AB-CR 97-4046-4	40 MM Ammunition Ready Service Room	205

# SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 14 of 249 pages. Volume III.

# EXPLOSIVE PHOTOGRAPHIC INDEX (Contid)


		TEST "A" & "B" (Cont'd)		
		U. BANNER (APA-60)	PAGE	
	85-353-9	500 lb., Aircraft Bomb	206	
BA-CR	85-353-10	350 lb., Aerial Depth Bomb	207	
		U.S.S. FALLON APA-EL)		
BA-CR	60-515-10	5"/38 Smokeless Powder Ready Service	208	
BA-CR	60-515-11	5"/38 Smokeless Powder Ready Service	209	
	60-515-12	5#/38 Projectile Ready Service	210	
	60-516-1	5"/38 Projectile Ready Service	211	
	60-516-2	20 MM Ammunition Ready Service	212	
	60-516-3	20 MM Ammunition Ready Service	213	
	60-917-9	40 MM Ammunition Magazine Stowage	214	
	60-917-10	Pyrotechnic Locker	215	
	60-917-11	Pyrotechnic Locker	216	
	60-918-1	40 MM Ammunition Ready Service	217	
	60-918-2	Small Arms Ammunition Stowage	218	
	60-918-4	5"/38 Smokeless Powder Magazine	219	
	6C-918-5 6O-918-6	5"/38 Projectile Magazine Stowage 5"/38 Projectile Magazine Stowage	220	
	87-2540-1		221	
	87-2540-2	5 <sup>n</sup> /38 Smokeless Powder Ready Service 5 <sup>n</sup> /38 Smokeless Powder Ready Service	222	
	62-4166-7	40 MM Ammunition Clipping Rocm	223	
	62-4166-9	20 MM Ammunition Ready Service	224	
	62-4166-11	20 MM Ammunition Ready Service	225 226	
		U.S.S. GILLIAM (APA-57)	220	
BA-CR	81-561-11	40 MM Ammunition in Bulwark Shields	227	
	U.S.S. LST-133			
BA-CR	234-381-11	Small Arms Ammunition Stowage	228	
	234-381-12	Pyrotechnic Locker	229	
AA-CR	234-381-7	20 MM Ammunition Ready Service	230	
AA-CR	234-1381-8	20 MM Ammunition Ready Service	231	
AB-CR	82-4218-4	20MM Ammunition Ready Service	232	
AB-CR	82-4218-5	20 MM Ammunition Ready & rvice	233	
0.5.0	r r m			

# SECRET

### SECKET

### EXPLOSIVE PHOTOGRAPHIC INDEX (Cont'd)

		TEST "A" & "B" (Cont'd)	DA ME
		U.S.S. IST-133 (Cont'd)	PAGE
AB-CR	82-4218-6 82-4218-7 82-4218-8	20 MM Ammunition Ready Service 20 MM Ammunition Ready Service 20 MM Ammunition Ready Service	234 235 236
		U.S.S. LST-545	
BA-CR BA-CR	92-931-1 92-931-3 92-931-5 76-941-2	40 MM Ammunition Magazine Stowage 20 MM Ammunition Magazine Stowage 20 MM Ammunition Ready Service Locker 4"/5 Rocket Heads	237 238 239 240
		U.S.S. LST-220	
P <b>A-</b> CR	81-975-7	5"/> Rocket Head Stowage	241
	•	<u>u.s.s. ici-615</u>	
	234-380-10 234-380-11	Pyrotechnic Locker Small Arms Ammunition Stowage	242 243
		U.S.S. LCI-327	
<b>∆∆-</b> CR	93-982-2	20 MM Amminition Ready Service	244
		U.S.S. ICI-620	
R <b>A-</b> CR	234-381-3	20 MM Magazine Reacy Service	245
		U.S.S. SALT LAKE CITY (CA-25) (Guided Nissle)	
	92-901-11	Special Guided Missle	246
	60-136-7 87-2539-11	Special Guided Missle Special Guided Missle	24 <b>7</b> 24 <b>8</b>
		U.S.S. BRULE (APA-66) (Guided Missle)	
AA-CR	87-2539-10	Special Guided Missle	249
SEC	REI		
Enclos	sure (D) to Di	rector Ship Material Serial 001500.	



Shows area of Test "A" explosion and the streamers of smoke which appear to be from pyrotechnics or tracer type ammunition. The arrow indicates the general position of the U.L.O. GALLIULE, (APA-69), and the U.D.S. ANDERSON, (10-411). Photo taken less than 3 seconds after the "A" explosion.

Photo. No. DA-CR-T2-11-11, Exp. #7.


### FFCFFI

Enclosure (D) to Director Ship Material Serial Yda C.



U.S.S. NEVADA (BB-36) - Before Able Shows a typical stowage of 14"/45 powder shoard a battleship prior to Test "A". Photo. No. BA-CR-92-429-6.

#### LECRET



U.S.S. NEVILA (SB-36) - before Alle Shows the Stell Leak of Tweet ho. A prior to Test "A". Ammunicion in photo, is accessed Ammunition, and Special Test Projection. Fhoto. No. bA-Ck-92-48)-D.

#### SECALT

Erclosure (D) to Director thip &ctoried posted 003500.

Pule 19 of 249 jags se Volume III.



U.D.D. PANIA (BB-36) - Refere Able phows the Special Test Ammunition in position in Turn t No. 4 prior to Test "A". Thoto. No. BA-CR-92-430-1.

#### 1111111

or Somme (L) to Linector Ship Material Serial 001500.



U.S.S. NEVADA (BB-36) - Before Able
Shows the Special Test Ammunition in position on the loading tray of the 5"/38 gun
in Mount No. 8. The projectile is plaster loaded and fored with a Mk. 53, Mod. 6
VT, nose fuze. The powder case is filled with SPCG Fowder. The complete round was
in this position for Test "A".
Photo. No. BA-CH 92-430-4.

#### SECELI




U.S.S. NEVADA (BB-36) - Before Able Shows the 20 MM Clipping Room, A-0204-M, prior to Test \*A\*. All ammunition in photo is Service Ammunition. Photo. No. BA-CR-92-430-5.



U.S.S. NEVADA (BB-36) - Before Able Shows the 40 MM Clipping Room, A-0208-H, prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-92-430-6.


#### SECELT



U.b.S. MNALA (20-30) - Before Able
Shows the 20 wh heady bervice box and its percentage of
ammunition to position for Test "A". Ammunition is Dervice
Ammunition.
Photo. No. BA-CK-92-430-7.

1111111

increaser (b) to birector thip Material Beriel 001500.




U.S.S. NEVADA (BB-36) - After Able
Shows the 20 MM Ammunition heady Service box and the degree of heat it had been subjected as a result of the Atom Pomb Flash. It is worthy to note that the inside paint was not damaged and that the Maximum and Minimum Thermometer registered no abnormal temperatures. The 20 MM Ammunition remained unharmed.
Photo. No. AA-CR-97-1535-7.

表別のマラエ



U.S.S. BEVALA (BB-36) - After maker
Shows the effect of shock on the 20 MM Ammunition Stowage.
The feilure of battens was marked. The Ammunition was not harmed.
Photo. No. AB-CH-76-1934-4.



U.b.b. REVALA (ch-3b) - After Baker bhows the effect of shock on the 40 MM Ammunition stowage. The fullure of batters and stanchions was marked. Photo. No. ab-Ck-76-1934-5.

#### ELGhlI




U.S.S. NEW YORK (BB-34) - Before Able Shows the 14"/45, projectile stowage in Magasine, A-57-M prior to Test "A". All projectiles are Service Ammunition. Photo. No. BA-CR-97-961-1.

#### BECKET


Enclosure (D) to Director Ship Material Serial 001500.

Page 28 of 249 pages. Volume III.




U.S.S. NFW YORK (BB-34) - Before Able Shows the typical stowage of 5"/51 Powder on board a Battleship prior to Test "A". Photo. No. BA-CR-97-961-2.

#### PECKET




U.S.S. NEW YORK (BB-34) - Before Able Shows the 5"/51 Projectile Stowage prior to Test "A". Photo. No. BA-CR-97-961-3.



U.S.S. NEW YORK (BB-34) - Before Able Shows the Special Test SPCG 5"/51 Powder in position in the Ready Service Box prior to Test "A". Photo. No. BA-CR-97-961-9.




U.S.S. NEW YORK (HB-34) - Before Able Shows the 5"/51 Ready Service Projectile Stowage in Mount No. 6. Ammunition as shown in the photo is a Special Test Ammunition. Photo. No. BA-CR-97-961-10.




U.S.S. NEW YORK (BB-34) - before Able
Shows the 3"/50 Reedy Service Lockers with emmunition in position prior to Test "A".
On Test "A" these lockers were subjected to exceedingly high temperatures from burnin,
Army Quartermaster Materials on display behind the lockers. After Test "A" pictures
AA-CR-87-2540-3 and AA-CR-87-2540-4 register the extent of damage.
Photo. No. BA-CR-97-961-12.

#### SECKET



U.S.S. NEW YORK (BB-34) - Before Able Shows the 14"/45 Powder Stowage in Magazine, A-54-M, prior to Test "A". Photo. No. BA-CR-97-962-12.




U.S.S. NEW YORK (BB-34) - Before Able
Shows the Special Test Ammunition in position on the left gun, gun trays in turret
No. 2 prior to Test "A". The Special Ammunition consisted of: One Armor Piercing
Projectile, 14"/45, blind loaded and fuzed with a Mk. 21 base Fuze; One bag of SFC:
Powder.
Photo. No. BA-CR-97-971-2.

#### SECRET



U.S.S. NEW YORK (BB-34) - Before Able Shows the Aircraft Domb Stowage in Magazine, G-32-M, prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-97-971-5.

# SECHET



U.S.S. NEW YORK (bb-34) - After Able Shows the 3"/50 Ready Service Locker (front view) after it had been subjected to intense heat caused from burning Army Quartermaster Materials in the rear. Temperatures were so extreme that the Maximum and Minimum Theremometer as seen in the photowas ruptured from its expending mercury. Surveillance test of the smokeless powder revealed no changes had occurred. Pre-test "A" picture, BA-CR-92-961-12 may be employed for comparison.


Photo. No. AA-CR-87-2540-3.

#### PFCFFI



U.S.S. NEW YORK (Eb-3/) - After Able Shows the intensity of heat subjected to the 3"/50 Feady Service Lockers from burning A my Quartermaster Materials on display. The Maximum and Minimum Thermometer inside the lockers were ruptured from expanding moreury indicating that the ammunition had withstood exceedingly high temperatures. Surveillance test of the smokeless powder revealed no change. Photo. No. AA-CR-87-2540-4.

#### SLURET




U.S.S. SAKATOGA (CV-3) - Before Able Shows the Incendiary Bomb Stowage prior to Test "A". Photo. No. BA-CR-92-457-5.

# SECKLI



U.S.S. SARATOCA (CV-3) - Before Able Shows the 20 MM Magazine, A-421-M, prior to Test "A". Photo. No. BA-CR-92-457-7.

# SECHLI



become Schooling (CV-3) - Before Able those the typical 5" Almoraft Rocket Read Stowage, A-2/5-1 prior to Tent "A".
Those, he ca-ch-92-457-9.


5 5 C 8 b 2

Enclosure (L) to director Ohip Reterial Devial 001500.

' ) age 41 of 247 pages. Volume III.



U.S.S. SARATOGA (CV-3) - Before Able Shows the 500 lb., bomb magazine, A-520-M prior to Test "A", Photo. No. BA-CR-92-559-2.



U.S.S. SAFACIGA (19-2) - Pefore Able

Shows the 500 lb. in. 20 lb., outle bomb magazine,

A-691-M prior to 7 to 5.7.


Photo. No. bA-64-92-339-7.

# SLLKET



U.S.S. SARATOGA (CV-3) - Hefere Alle Shows the 100 lb., and 1000 lb., book magazine, A-620-M, prior to Test "A". Photo. No. BA-CR-92-559-8.


PFCFF



W.S.D. MARATCCA (CV-3) - Before Able Shows the 5" powder magazine, A-611-M with pewder in position for Yest "A". Those, No. BA-CR-92-559-10.

(D) to Director Ship Naterial Serial 001500.

Page 45 of 249 pages. Volume III.




U.S.S. DARATOTA (CV-3) - Before Able Shows the torpedo ready service stowage on the m.zzanine deck (O2 level) prior to Test "z". Photo. No. bA-CH-92-560-2.

# BCHET



C.O.D. DARATOOA (CV-3) - before Alle Thoms the upper 5"/38 hamiling room for Yount Tirlor to Test "A". Photo. Wo. FA-CR-92-560-4.

Enclosure (1) to Director Chip Material Nerlet 1935.80.



U.D.S. DAMARCHA (CV-3) - before Able Shows the upper 5"/38 handling room for Mount 7 prior to Test "A". Photo. No. BA-(R-94-560-5.


# 

crelieure (t) to limetor Stip Weterfel Serial 001000.




b.0.5. DarkTODA (CV-3) - Fefore Ablc Shows the (L2F) Special: Test Ammunition in position in Hount, No. 7 prior to Test "A". Photo. No. BA-Ch-92-560-6.

# SECRLT



U.S.S. SARATOGA (CV-3) - Before Able Shows the Special Test Ammunition in position in Mount No. 5 prior to Test "A". Photo. No. BA-CR-92-560-8.

### BECKET



U.S.O. SARATOGA (CV-3) - Before Able Shows the 40 kM Clipping Room and typical stowage bettens in position prior to Test "A". Photo. No. bA-CR-92-560-10.

医异位异亚亚




U. .S. DahATCGA (CV-3) - Before Able
Shows the 500 lb., general purpose, aircraft bombs,
AN-M64Al, plaster loaded and fuzed, in position prior to Test "A".
Fhoto. No. DA-CR-63-1560-3.

-12 C -12 T




U.S.S. SARATOGA (CV-3) - Before Able Shows the 500 lb., general purpose, aircraft bombs, AN-M64A-1, placter loaded and fuzed in position prior to Test "A". Photo. No. BA-CR-63-1960-6.

# SECRET



U.S.S. SAKATOGA (CV-3) - Before Able
Shows the 11".75 Aircraft Rocket (Tiny Tim) in position
for Test "A". The complete rocket was inert.
Photo. No. BA-CR-63-1560-7.

# SECRET




U.S.S. SARATOGA (CV-3) - before Able Shows the 11".75 Aircraft Rocket (Tiny Tim) in position price to Test "A". The rockets were completely inert. Photos No. BA-CR-63-1560-8.

Section (1) to Director Ship Material Seriel 001500,



"U.S.S. SAKATONA (CV-3) - Before Able
AShows the 350 lb., mircraft death bombs, which is how. I,
plaster loaded and fazed, in position prior to rest "A".
Photo. No. BA-Kh-63-1567-9.


# LCRLT



U.S.S. SANATUGA (CV-3) - Before able Shows the 350 lb., eircraft depth bombs, AN-Mk. 54 Mod. 1, pleater loaded and fuzed, in position prior to Test "A". Photo. No. BA-Ch-63-1500-10.

# SECRET

Enclosure (L) to Director to by Maccriel Serial Online.



U.S.S. SAKATOGA (CV-3) - Before Able

Shows the 5"/O Aircraft Rockets assembled and in


publication prior to Test "A".

Publication BA-CK-63-1560-12.

#### SECI

Enclosed (1) to Director Ship Material Serial 001500.


Fage 58 of 249 pages. Volume III.



U.L.S. SARATOGA (CV-3) - Pefore Able Shows the 350 lt., aerial doubt bombs, AN-Mk. 54, Mod. 1, plaster lowed and fused, in position prior to Test "A". Photo. No. EA-CK-63-1563-1.


# SECELT

inclosure (D) to Pirector Ship Material Legist 001500.




V.S.S. SARATOGA (CV-3) - Before Able Shows the 500 lb., general purpose, sircraft bomb, AN-M6WAl, plaster loaded and fuzed ir position prior to Test "A". Photo. No. BA-Ch-63-1563-4.

# SECRET



U.S.S. SARATOGA (CV-3) - Refore Able Shows the Special Test Aircraft Torpedo, Mk. 13, in position prior to Test "A". The warhead is inert loaded but the flask is fully charged. Photo. No. BA-CR-63-1563-5.

# SECRET




U.D.D. SARATORA (CV-3) - Perfore Alle Shows the assembled 5".0 Alrem th Locketo in confit per prior to Test "A". Photo. No. FA-CR-63-1563-6.

# PEFFL

nelosure (b) to Director Ship Material Seriel 0016 %.

lage 62 of 249 jages. Volume Tit.




U.S.S. SARATOGA (GV-3) - Before Able Shows the ll".75 Aircraft Rockets, (Tiny Tim), Inert loaded, in position prior to Test "A". Photo. No. BA-CR-63-1563-7.

#### SECHLI

Enclosure (D) to Director Ship Meterial Social 001500.


Page 63 of 249 pages. Volume III.



U.b.s. INLEHABLING (CVI-22) - refore Able brows the 1700 H., armor Piercing, Aircraft Fomb, stownge in Magnaire A-511-h prior to west "A". bombs are Service combs.
Thoto, bo. PA-CR-63-220-2.

# SECHEI

Enclosure (D) to Director Bhdy Material Carrel Oct 100.




U.S.S. INDEPENDENCE (CVI-22) - Before Able Shows the pO Cal. Small Arms Ammunition Stowage in magazine, C-507-M, prior to Test "A". Photo. No. EA-CR-63-320-5.

# SECHLI




U.S.S. INDEPENDENCE (CVI-22) - Before Able Shows the 40 MM Ammunition Stowage in Magazine, C-0303-M prior to Test "A". All ammunition is service ammunition. Photo. No. PA-CR-63-320-7.

# SECRET




U.S.S. INDEPENDENCE (CVI-22) - Before Able Shown the Aircraft Ready Torpedo Stowage in Compartment C-101-B prior to Test "A". Torpedoes are Service Torpedoes. HBX loaded. Photo. No. RA-CR-63-320-11.

#### SECKET




U.S.S. INDEPENDENCE (CVL-22) - Before Able Shows the 40 MM Magazine, A-506-M and Blast Instrument in position for Test "A". All ammunition is Service Ammunition. Photo. No. ba-Ck-97-414-5.

### **東京では下**国




U.D.C. INDEREDDINGE (CVL-22) - Refore Able
Shows the Femb Fuze and Detenator Storage in Magazine,
A-411-M prior to Test "A". Fuzes and Detenators are service.
Photo. No. RA-CR-92-414-6.

# SECRET




U.S.S. INDEPENDENCE (CVL-22) - Hefore Able Shows the 5" Aircraft Rocket Motor Stowage in Magazine, A-4132-M prior to Test "A". All Hocket Motors are Service. Photo. No. RA-CR-92-414-8.

# LEGBLT



U.S.S. INDEPENDENCE (CVI-22) - before Able Shows the 260 lb Fragmentation bomb stowage in Magazine, A-511-M prior to Test "A". Bonbs in photo are service bombs. Photo. No. hA-Ch-92-414-10.

## SECELT



U.S.S. INDEPENDENCE (CVL-22) - Before Able Shows the 40 MM Clipping Room, C-0303-M, prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-92-429-5.


## SECKET



U.S.D. PENSACOLA (CA-24) - Pefore Ablo Shows the 20 MM clipping room on the 02 deek level prior to Test "A". Photo. No. FA-Ch-15-12


## SECLLT

knolosure (b) to Mireutor Ship Laterial Scriet 001500.




U.D.D. FENSACOLA (CA-2%) - Before Able Shows the typical stowage of 5"/25 powder on board a Cruiser prior to Test "A". Fhoto. No. BA-CR-S1-315-4.

Lieuvening (%) to director Whip Material Serial 001500.




U.S.S. PENSACOLA (CA-24) - Before Able Shows the 5"/25 Powder Magazine, A-426-M, prior to Test "A". Fhoto. BA-CR-S1-315-6.

SLCAL1



U.S.S. PENSACOLA (CA-24) - Before Able Shows the 8"/55 Powder Magazine, A-411-M, prior to Test "A". Photo. No. BA-CR-81-315-10.




U.S.S. PENSACOLA (CA-24) - Before Able Shows the 8"/55 powder magazine, A-414-M, prior to Test "A". Photo. No. BA-CR-21-315-11.


## SECKET

Enclosure (D) to Director Ship Material Serial 001500.


hage 77 of 249 pages. Volume III.



U.S.S. PENSACOLA (CA-24) - Before Able Shows the 40 MM Ready Service Stowage on the main deck, frame 98, prior to Test "A". Photo. Ho. BA-CR-SL-316-1.




U.S.S. PANSALOLA (CA-24) - Before Able Shows the 8"/55 Powder Magazine, forward group, prior to Test "A". Photo. No. BA-CH-92-323-5.



U.S.S. PENSACOLA (CA-24) - Before Able Shows the 40 MM Ammunition Stowage in Magazine, D-100-M, prior to Test "A". Photo. No. BA-CR-92-323-9.


and the same of th




U.S.S. PENSACOLA (CA-24) - Before Able Shows the 5"/25 ready service box with percentage of test ammunition in position for Test "A". This box was located aft on the AA deck. Photo. No. BA-CR-92-323-10.

Enclosure (D) to Director Ship Material Serial 001500.


Page 81 of 249 pages. Volume III.




U.S.S. PENSACOLA (CA-24) - Before Able Shows the 5"/25 Ready Service Box in the closed position for Test "A". Photo. No., BA-CR-92-323-11.



U.S.S. PENSACOLA (CA-24) - Before Able Shows the Shell Deck with projectiles in position in Turret, No. 2, prior to Test "A". Photo. No. BA-CR-92-324-1.



U.S.S. PERSACOIA (CA-24) - Before Able
Shows the Special Test Ammunition in the loading trays of Turret, No. 3, prior to
Test "A". The test ammunition consisted of; one high capacity loaded and plurged
projectile, and one armor piercing loaded projectile.
Photo. No. BA-CR-92-324-2.



U.S.S. PENSACOLA (CA-MA) - Hefere Able Shows the Special Test Ammunition (One bay of SMC2 POTDER and one round 84/55 Armor Piercing Projectile - plaster located and based with Mk. 21, base fuze) in the loading tray of the port gun in Turret, No. 4, prior to Test \*A\*. Photo. No. BA-CB-92-324-3.



U.S.S. PENSACOLA (CA-74) - After Atle
Shows the location of the fire adjacent to turnet No. 4
and its effect on the turnet. Heat generated from the
burning Quartermaster materials on display caused slight
scorching to charring of paint on the turnet. Ammunition
inside the turnet and ammunition on the gun trays was not
effected.
Photo. No. AA-CR-92-1778-2.

## SECHLI

Enclosure (D) to Director Ship Material Serial Octions.

Page 86 of 249 pages. Volume III.



U.C.D. Philadella (the A) = Alteralia Shows the location of the line edge est to turnet. We also like the standard of the location of the location when the result will be a recovered to charming of mint on the turnet. Almonition in the the turnet and ammunition on the turn becomes was not effected. Photo. No. AA-C-C-17/2- ...

## SECLET

Enclosure (D) to Director Ship Later of Larried Colors.

Page 87 of 249 pages. Volume III.

The second secon



U.S.S. PENSACOLA (CA-24) - After Able Shows the Special Test Ammunition in the loading trays of Turret No. 4. The ammunition was not harmed in any respect. Photo. No. AA-CR-92-1778-4.

# ECKLI

nclosure (D) to Director Ship Material Serial  $001^{11}$   $\odot$ .



U.L.S. PENDACOLE (Cn-24) - After Atte Shows the effect of blast to the 20 km loaded magazines in the 20 MM Ready Lervice Room. A feasible securing device should be incorporated in the present design to prevent the magazines from bouncing out when subjected to excessive upward motion.

Photo. No. AA-CR-92-1778-5.

## SECKET

Enclosure (D) to Director Ship Material Seriel Selection


Fage 89 of 249 pages. Volume III.

# 7 L 0530-40 and 0




U.S.A. HINDECLA (CA-ZA) - After Able
Shows the extent of damage and intensity of heat as a
result of the Atom Bomb Flash. It is worthy to note that
the paint inside the 5"/25 Ammunition Ready Service Locker
was not harmed nor did the maximum and minimum register
any abnormal temperatures. The ammunition suffered no
damage.
Photo. No. AA-CR-87-2539-7.

## SECHET



N.S.S. PENSACCIA (CA-AL) - After Baker Shows the displacement of the 8"/55 Armor Fiercing Projectile assessed by shock. The projectile was not damagen. Photo. No. Ab-Ck-80-1618-12.

SECAET




U.S.S. PENSACOLA (CA-24) - After Baker Shows the effect of shock to 8"/55 Powder Stowage. The failure of battens and stanchions was marked. Photo. No. AB-CR-80-1675-4.


# $\Sigma L C E E T$



U.S.S. PENSACOLA (CA-24) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage. The failure of bultons and stanchions was marked. Photo. No. AB-CR-80-1676-1.



U.S.S. PENSACOLA (CA-24) - After Baker Shows the effect of shock to the 5"/25 Ammunition Stowage. The failure of battens and stanchions was marked. Photo. No. AB-CR-80-1676-2.



U.S.S. PENSAGOLA (CA-24) - After baker Shows the effect of shock to the 84/55 powder storage and the extent of ammunition displacement. The failure of batters are stanchions was marked.

Photo. No. AB-CR-80-1676-3.

SECFFI

Enclosure (D) to Director Ship Material Serial 001500.

Page 95 of 249 pages. Volume III.



U.S.S. PENSACOLA (CA-24) - After Baker Shows the effect of shock to the 40 mm Ammunition Stowage. The failure of battens and stanchions was marked. Photo. No. AB-CR-80-1676-5.

## BECRET



b.b.b. Ph. DACCIA (CA-DA) - After baker
hows the displacement of SM/55 projectiles in the thell beek Stowage. This displacement was a result of the vessel teing subjected to severe shock. The distortion of the deca structure at the shell deck level can be reen. A distance of 60 mas scasured between the cotating structure are the fixed ethic type.
Froto. No. Ab-Ch-80-1677-16.

111111

brolomure (b) to birector thip Deterior Derivi Oblices.

tage 9% of 249 pages. Volume III.



U.D.D. PENNACOLA (CA-2A) - After Haker
Shows the displacement of 8"/55 projectiles in the
Shell Deck Stowage. This displacement was a result of
the vessel being subjected to severe shock. The distortion
of the deck structure at the shell deck level can be seen
a distance of 6" was measured between the retating structure
and the fixed structure.
Photo. No. AB-CH-8C-1678-1.

## EEGEET '

Enclosure (L) to Director Ship Natural Serial 001500.

Fage 98 of 249 pages. Volume III.



U.S.S. PENSAUCIA (CA-2A) - After baker Shows the displacement of 8"/55 projectiles in the Shell back Stowage. This displacement was a result of vessel leins subjected to severe shock. Photo. No. Ab-Ch-80-1678-2.

SECHLT .


Enclosure (D) to Director Shi: Material Serial Colsco.

Fage 99 of 249 pages. Volume III.



U.D.S. PENSALOLA (CA-14) - After baker Shows the misalignment of the deck and the displacement of the 8"/55 projectile. The displacement was a result of the vessel being subjected to severe shock. Photo. No. Ab-CR-80-1679-6.

## 三年で 37 月1



U.S.S. PENSACOLA (CA-24) - After Baker Shows the displacement of the 64/24 ready service box caused by blast from the Atom Bomb. Photo. No. AB-CR-100-4209-1.


## SECLET

Enclosure (D) to Director Ship Material Lariah of 1500.




U.S.S. PANSACOLA (CA-24) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage. The failure of battens and stanchions was marked. Photo. No. Ab-CR-100-4205-3.

# SFCHET



U.S.S. SALT LAKE CITY (CA-25) - before Able Shows the  $5^{\rm H}/25$  Ammunition Stowage in the Ready Service Box prior to Test "A". Photo. No. BA-CR-92-901-10.

SECHET



U.S.S. SALT LAKE CITY (CA-25) - After Able Shawe the extent of damage and intensity of heat as a result of the Atom Bomb Flash. It is worthy to note that the paint inside the 5"/25 Ammunition Boady Service Locker was not harmed nor did the Maximum and Minimum Thermometer register any abnormal temperatures. The ammunition suffered no damage. Fhoto. No. AA-CR-87-2539-8.



U.S.S. SALT LAKE CITY (CA-25) - After Able
Shows the extent of damage and intensity of heat as a result of the Atom Fomb Flash.
It is worthy to note that the paint inside the 5"/25 Ammunition Ready Service Locker
was not harmed nor did the Maximum and Winimum Thermometer register any abnormal
temperatures. The ammunition suffered no damage.
Photo. No. AA-CK-87-2539-9.




U.S.S. STACK (DD-406 - Before Able Shows the Torpedo Impulse Charges in position prior to Test "A". Photo. No. BA-CR-81-415-4.

LECHET




U.S.S. STACK (LD-406) - Refore Able Shows the depth charge marker stowage prior to Test "A". Photo. No. BA-Ch-81-415-5.

### SECKET




U.S.S. STACK (DD-406) - Refore Atle Shows the Depth Charge Impulse Stowage. Photo. No. BA-CR-81-415-6.

bnclosure (D) to Director Ship Material Cerial 001500.



U.S.S. STACK (DD-406) - Before Able Shows the depth charges in position prior to Test "A". Photo. No. BA-CR-81-415-8.

### SECHLI



U.S.S. ANDERSON (DD-411) - Before Able Shows the Depth Charges, Mk. 6 in position. Photo. No. RA-CR-85-447-1.

knelosure (D) to Director Ship Material Serial 001500.


Page 110 of 249 pages. Volume IXI.



U.S.S. HUGHES (LD-410) - Before Able Shows the 20 MM Ammunition in position in the 20 MM Ready Service Box prior to Test "A". Photo. No. BA-CR-81-48-4.


Enclosure (D) to Director Ship Material Serial 301500.

Page 111 of 249 pages. Volume III.



U.S.S. HUGHES (DD-410) - Before Able Shows the 40 MM Clipping Room, B-108-M prior to Test "A". Photo. No. BA-CR-F1-486-5.


RFFFFE



The second second designation of the second second

. Moreover, and the structure of arrival  $\lambda$ 

Control (118 of 12 or wheel or 21 me 111 a



U.S.S. HUGHIS (DD-AlO) - Before Aide Shows the 5"/38 powder magazine, C-302-M, prior to Test "A". Photo. No. BA-GR-81-486-9.



U.S.S. HUGHES (DD-410) - Before Able Shows the 5"/38 Upper Handling Room of Cun No. 2 prior to Test "A". Photo. No. BA-CR-81-486-10.



"No.s. HUGHES (DD-410) - Before Able
"Shows the 5"/38 Projectile Stowage, A-407-M prior
to Test "A".
Photo. No. bA-CR-81-486-11.

SECHET



U.S.S. HUCHES (DD-410) - Before Able Shows the 5"/38 gun house with a round of powder in the receiving position prior to Test "A". Photo. No. BA-CR-81-561-1.

Enclosure (D) to Director Ship Material Serial 001500.

Page 117 of 249 pages. Volume III.




U.S.S. HUGHES (DD-410) - After Baker Shows the effect of shock on the 5"/38 Upper Handling Room. Slight dents were detected in a few rotating bands on the projectiles. Photo. No. AB-CR-76-1931-1.




U.S.S. HUGHES (DD-410) - After baker Shows the effect of shock on the 5"/32 Fowder Stowage in the Upper Handling Room. Dents were inflicted in some of the Cartridge Cases ranging from alight to severe. The failure of battens and standhiums was marked. Photo. No. AB-CR-76-1931-2.

### SECELT



U.S.S. HUCHES (LD-410) - After Baker Shows the effect of shock on the 5m/38 Powder and Projectile Storage in the Upper Handling Room. Few projectiles rotating bands and cartridge cased were dented ranging from slight to severe. The failure of battens and stancisions was marked. Photo. No. AB-CR-76-1931-3.

#### SECREI



U.L.S. HUGHES (DD-410) - After Baker Shows the effect of shock on the Upper Bandling Room of No. 4, 5%/38 Gun Mount. Rotating Bands on a few projectiles were dented. 5%/38 Projectile Rendy Envice Racks failure was marked. Photo. No. AB-CR-76-1931-4.

### SECHLI




N.S.S. HUGFES (DD-410) - After Baker Shows the Upper Handling Room of No. 4, 5"/38 Gun Mount and the extent of displaced ammunition caused from shock. The failure of battems was marked. Photo. No. AB-Ch-76-1931-5.

### SEGRET

Enclosure (L) to Director Ship Material Serial 001500.

Page 122 of 249 pages. Volume III.



U. S. HUCHES (DD-410) - After Baker Shows the effect of shock on the 5"/38 Projectile Stowage in Magazine, C-303-M. The failure of battens and stanchions was marked. Estating bands on a few of the 5"/38 Projectiles were dented. Photo. No. AB-CR-76-1931-6.

## SECHET

Enclosure (b) to Lirector Ship Materi. Serial 001500.

Page 123 of 249 pages. Volume III.



U.S.S. HUGHES (DD-410) - After Baker Shows the effect of shock on the 5m/38 Powder Stowage in Magazine, C-40/-M. The failure of battens and stanchions was marked. Few Powder Tanks and Cases were dented. Photo. No. 4B-Ch-76-1931-7.

## SECHET



U.S.S. HUGHES (ID-410) - After Baker Shows the effect of shock on the 40 MM Ammunition Stowage in the 40 MM Clipping Room on the Main Deck, Frame 135. The failure of battens and stanchions was marked. Ammunition as seen in this photo remained unharmed. Photo. No. AB-CR-76-1932-3.





MR R1 -418

U. D. ... hAINhRI(HI (LL-L19) - Hefore Able Shows the Fyrotechiae Stowers on the Bridge Level. No. FA-CK-81-418-4.

Enclosure (D) to Director Ship Material Serial Oction. SECHET

Page 126 of 249 pages. Volume III.




U.S.S. WAINWHIGHT (DD-Ale) - defore Able Shows the exposed 40 MM Amminition in the bulwark shields. Photo. No. HA-CR-81-416-6.


BECLLI



U.S.L. LAMSON (DD-367) - Before Able Shows the Depth Charges, Mk. 9 in position prior to Test "A". Photo. No. BA-CR-81-316-11.



U.S.S. CONYNGHAM (DD-371) - Before Able Shows the special test, loaded and plugged, 5"/38 projectiles, in position in the Ready Service Box prior to Test "A". Photo. No. RA-CR-92-289-1.



U.S.S. CONYNGFAM (DD-371) - Refore Arla Shows the 5"/38 powder in the Ready Service Box prior to Test "A". Photo. No. EA-CR-92-289-2.

### BECCETT




U.S.S. RHIND (DD-404) - Before Able Shows the (L&P) Special Test 5"/38 Projectile in position on the Gun Tray. Photo. No. BA-CR-81-314-4.

### BECRET

wt )

. There .




U.S.S. MUGFORD (DD-389) - Before Able Shows the (L & P) Special Test Ammunition in position in the Hoist and Ready Service Stowage. Photo. No. 14-CR-92-413-4.


## BICKET



U.S.S. MUGFORD (DD-389) - Before Able Shows the 5"/38 AAC, loaded and plugged projectiles in the Upper Hanlding Room of Mount 5, prior to Test "A". Photo. No. BA-CR-92-413-6.



U.S.D. MUGFORD (DD-389) - Before Able Shows the Special Test Projectiles, 5"/38 in position in the Ammunition Hoist and the Ready Service Stowage. Photo. No. bA-CR-92-413-9.



U.S.D. MUGRCHD (DD-389) - Before Able Shows the 5"/38 White Phosphorous Projectiles in position in Mount 4 Upper Handling Room, prior to Test "A". Photo. No. BA-CR-92-414-2.

SECKLT




U.S.S. HALPH TALEOT (DD-390) - Before Able Shows the 5"/38 Special Test Powder (SPCG) in the Upper Handling Room of Mount 3 prior to Test "A". Photo. No. BA-CR-92-325-2.

EEChLT

enclosure (D) to Director Ship Material Serial 901500.

Page 136 of 249 pages. Volume III.



U.S.S. RALPH TALBOT (DD-390) - Before Able Shows the 5"/38 Special Test Powder (SPCG) in the Ready Service Box prior to Test "A". Photo. No. BA-CR-92-325-4.



U.S.S. PRINZ EUGEN (CA-Ger) - Before Able Shows the 8" powder stowage. Photo. No. BA-CR-92-930-/..


## 




U.S.S. Phinz EUGEN (CA-Ger) - hefore Able Shows the 8" Fowder Stownge. Photo. No. BA-CR-92-930-5.



U.S.S. PHINZ EUGEN (CA-Ger) - Before Able Shows the 8" Projectile Stowage. Photo. No. BA-CR-92-930-6.




U.S.S. PRINZ EUGEN (CA-Ger) - Refore Able Shows the 10.5 CM Powder Stowage. Photo. No. BA-Ck-92-930-7.



U.S.S. PRINZ EUGEN (CA-Ger) - Refore Atle Shows the projectile func locker and stowers. Thoto. No. EA-CR-92-930-8.


### SEVERT



U.S.S. NACATO (Ex-Jap BB) - before Able Shows the 350 lb., aerial depth bomb, AN-Mk. 54, Mod. 1, HBA loaded and plugged in position for Test MAW. The depth bomb was located on the uppermost deck, frame 320, starboard side.


Photo. No. BA-CR-76-131-5.

### SECRET



U.S.S. NAGATO (Ex-Jap BB) - Before Able Shows the Torpedo Warhead, Mk. 13, and the typical method of securing it to the deck. Fhoto. No. BA-CR-76-131-8.

## SLCKET




U.S.B. NACATO (Ex-Jap 18) - before Able Shows the 350 lb., serial depth bomb, AN-Mk. 54, Mod. 1, MBX loaded and plugged, in position for Test "A". The depth bomb was located on the uppermost deck, frame 20, stbd. side. This bomb was later blown from its securing cables and forward 6 feet. Finto. No. bA-CR-75-131-10.


Shukr T



U.S.S. NAGATO (Ex-Jap) - Before Able Shows the Warhead, Mk. 13, HbX loaded and plugged, (no exploder mechanism) secured in position for Test "A". The warhead was located on the uppermost deck, frame 145, port side. Photo. No. BA-CR-76-131-11.



U.S.S. NAGATO (Ex-Jap BB) - Before Able Shows the 500 lb., general purpose, aircraft Lomb, AN-M64A1, TNT loaded and plugged, in position for Test "A". The bomb was located on the uppermost deck, frame 74, port side. Photo. No. BA-CR-76-131-12.



U.S.S. NAGATO (Ex-Jap BB) - Before Able Shows the Armor Piercing, 40 CM, projectile stowage in the Shell Room of No. 4 Turret. Photo. No. BA-CR-60-917-1.

## SECKET



U.S.S. NACATO (Ex-Jap BB) - Before Able Shows the 25 MM Ammunition (Japanese Munition) stowage in the forward port magazine. Photo. No. BA-CR-60-917-5.

## SECKLI




U.S.S. NACATO (Ex-Jap Bb) - Before Able Shows the 40 CM, Common, projectile stowage on the Shell Leck of No. 1 Turret. Photo. No. BA-CR-60-917-6.

## 



U.S.S. NAGATO (Ex-Jap RB) - Before Able Shows the method of securing and the 5" aircraft rocket heads, Mk, 10, Mod. 0, TNT loaded and plugged in position for Test "A". The rocket heads were located on the hoat deck, frame 140, starboard side. Photo. No. BA-CK-76-1799-1.

### SECEET



U.S.S. NAGATO (Ex-Jap BB) - After Able
Shows the 350 lb., Aerial Depth Bomb, AN-Mk. 54, Mod. 1, HEX
loaded and plugged, after Test "A". As shown in the photo, the
bomb was blown forward 6 ft. by the blast. The blast was so
severe that it caused the Sister Hook on the securing cable to
straighten allowing the whole unit to become unsecure. The
bomb was not damaged in any respect See Pro-test "A" picture,
BA-CR-76-131-10 for comparison.
Photo. No. AA-CR-87-2539-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 152 of 249 pages. Volume III.




U.S.S. NAGATO (Ex-Jap BB) - After Able
Shows the Sister Hook on the end of the securing cable
which was disfigured by the blast allowing the Aerial
Depth Bomb located on the uppermost deck, frame 20,
starboard side to become unsecure and blown forward 6 ft.
The following related pictures may be reviewed: BA-CR-76131-10, AA-CR-87-2539-2, and AA-CR-87-2539-4.
Photo. No. AA-CR-87-2539-3.

#### SELLET

> 5%

Enclosure (D) to Director Ship Material Serial GO1500.

Page 153 of 249 pages. Volume III.




U.S.S. NAGATO (Ex-Jap hB) - After Able
Shows the 350 lb., Aerial Depth Bomb, AN-Mk. 54, Mod. 1,
HBX loaded and plugged. As shown in the photo the bomb
was blown forward 6 ft. by the blast. The blast was so
severe that it caused the Sister Hook on the securing cable
to stricten allowing the whole unit to become unsecure.
See Pre-test "A" picture BA-CR-76-131-10. The bomb was
not demaged in any respect.
Photo. No. AA-CR-87-253°-4.

### SECELI

Enclosure (b) to Director Ship Material Serial 001500.

Page 154 of 249 pages. Volume III.




U.S.S. NAGATO (Ex-Jap BB) - After Able
Shows the 500 lb. general purpose, Aircraft bomb, AN-M6/Al, TNT loaded and plugged
after Test "A". The Tail Fin ASSY, suffered slight damage from falling detris from
the superstructure. Although the wooden decks in the vicinity of the homb were
slightly scorched, the preservative paint on the homb casing showed no signs of
excessive temperatures. The entire unit as seen in the photo was moved 5" forward the blast due to the failure of the deck planking. Fre-tait "A" picture, bA-CR-76131-12, may be employed for comparison.
Photo. No. AA-CR-87-200-5.

#### SECKLI



1.S.S. NAGATO (Ex-Jap BB) - After Able
shows the Jet Assisted Take-off Unit. The Unit was a Service Unit being loaded with
rotassium perchlorate, asphalt, and oil, An igniter was not installed in the Unit for
the Test. As seen in the photo, the Unit was subjected to falling debris. Since the
linit is considered unserviceable should it be dropped from a height of 3 ft. this decision was assumed. Although the wooden decks in the civinity were slightly scorched the
linit exhibited no signs of excessive temperatures. An eigen of torpedo warhead, Mk. 13
many be seen in the background. Pre-test "A" picture RA-Ch-76-131-9 may be employed for
comparison. Photo. No. AA-CR-87-2539-6.

LECKET




U.S.S. PILOTFISH (SS-386) - Before Able Shows the 40 NM Ammunition in the Ready Dervice Locker. Photo. No. BA-CR-97-962-4.

LLLLIT



U.S.S. PILOTFISH (SS-386) - Before Able Shows the Pyrotechnic Stone; e in the Pyrotechnic Locker. Photo. No. BA-CR-97-962-9.



U.S.S. SKATE (SS-305) - Before Able Shows the typical 5".0 magazine stowage. Photo. No. BA-GR-63-946"/

Enclosure (D) to Director Ship Material Serial 001500.

Page 159 of 249 pages. Volume III.



U.S.S. SKATE (SS-305) - Before Able Shows the percentage of service allowance ammunition placed in the ready service locker for Test "A". Photo. No. BA-CR-63-946-2.

## SECKET




U.S.S. SKATE (SS-305) - After Able Shows the condition of the 40 MM Ready Service Box after it had been subjected to terrific blast. Amountain within the Ready Service Box remained unharmed. Photo. No. AA-CR-92-1778-7.

## RECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 161 of 249 pages. Volume III.



U.E.S. SKATE (SS-305) - After Able Shows the condition of the 40 MM Ready Service Box after it had been subjected to terrific blast. Ammunition within the Ready Service Box remained unharmed. Photo. No. AA-CR-92-1778-8.

 $\underline{\mathbf{S}} \underline{\mathbf{L}} \underline{\mathbf{C}}_{n} \underline{\mathbf{R}} \underline{\mathbf{L}} \underline{\mathbf{T}}$ 


Enclosure (L) to Director Ship Material Serial 001500.

Page 162 of 249 pages. Volume III.




U.S.S. SKATE (SS-305) - After Able Shows the condition of the 5" Ready Service Fox after it had been subjected to terrific blast. The Assumition within the Ready Service Fox remained unharmed. Photo. No. AA-CR-92-1778-9.

## SECRLT



U.S.S. SEARAVEN (SS-196) - Before Abla Shows the 4"/50 Ready Service Locker in position for Test "A". Photo. No. BA-GR-97-589-5.


# SEGRET



U.S.S. SEARAVEN (SS-196) - Before Able Shows the 4"/50 Ammunition in the Ready Service Locker. Photo. No. BA-CR-97-589-6.


Enclosure (D) to Director Ship Material Serial 001500.

Page 165 of 249 pages. Volume III.



U.S.S. SEARAVEN (SS-196) - Before Able Shows the 50 Cal., Ammunition in position. Photo. No. BA-CR-97-589-10.

LEGRET




U.S.S. SEARAVEN (SS-196) - Refore Able Shows the 50 Cal., Ready Service Locker in the closed position. Photo. No. BA-CR-97-589-11.

## SECHET



U.S.S. SEARAVEN (SS-196) - Before Able shows the 4"/50 Powder Stowage below the Crew's Mess in position.
Photo. No. BA-CR-97-589-12.




U.S.S. SHARAVEN (SS-196) - Before Able Shows the Mk. 2, 55 lb., TNT loaded, Lemolition Charge in position. Photo. No. BA-CR-97-962-2.

SECALT



U.S.S. CARLISLE (APA-69) - Before Able Shows the 500 lb., general purpose, Aircraft Bomb, AN-M6/Al, TNT loaded and plugged, in position prior to Test "A". The bomb was located in the No. 1 Cargo Hold, frame 54, atbd. side. Photo. No. BA-CR-93-96-11.

## BECKET




U.S.S. CARLISIE (APA-69) - Before Able
Shows the 350 lb., Acrial Depth Bomb, AN-Mk. 54, Mod. 1,
HBX loaded and plugged, in position prior to Test "A".
The bomb was located in the No. 1 Cargo Hold, frame 54,
port side.
Photo. No. BA-CH-93-96-12.

#### SECRET



U.S.S. CRITTINDEN (APA-77) - Before Able Shows the 350 lb., aerial depth bomb, AN-Mk. 54, Mod. 1, HBX loaded and plugged, in position for Test "A". The bomb was located on the Ol deck, frame 45, port side. Photo. No. BA-CH-81-906-2.



U.S.S. CRITTENDEN (APA-77) - Before Able Shows the 5CO lb., general purpose, aircraft bomb, AN-M64Al, TNT loaded and plugged, in position for Test "A". This bomb was located on the Ol deck, frame 42, stbd. side Photo. No. BA-CR-81-906-4.

SECKET



U.S.S. CRITTENDEN (APA-77) - After Able
Shows the final position of the 500 lb., general purpose, aircraft bomb, AN-M64Al, TNT
loaded and plugged after it had been blown 12 feet aft and 7.2 feet inboard by the blast.
The original position of the bomb was on the 01 deck, frame 42, stbd. side. The Tail
Fin Assy. received negligible damage; indications of excessive temperatures were not
present.
Photo. No. AA-CR-60-145-4.

SECHET



U.S.S. CRITTENDER (APA-77) - After Able
Shows the final position of the 500 lb., general purpose, aircraft bomb, AN-M64Al, TNT
loaded and plugged after it had been blown 12 feet aft and 7.2 feet inboard by the blast.
The original position of the bomb was on the 01 deck, frame 42, stbd. side. The Tail
Fin Assy. received negligible damage; indications of excessive temperatures were not
present.
Photo. No. AA-CR-60-145-5.

SECELI



U.S.S. CRITTENDEN (APA-77) - After Able
Shows the 350 lb., aerial depth bomb, AN-Mk. 54, Mod. 1, HEX loaded and plugged after
it had been torn from its securing cable and blown 6 feet inboard by the blast. The
Tail Fin Assy. received extensive damage (beyond repair for personnel in the field) and
the preservative paint on the bomb casing was slightly scorched by the heat flash of
the A bomb. The original position of the bomb was on the Ol deck, frame 48, stbd.,
side.
Photo. No. AA-CR-60-145-6.

SECRET



U.S.S. CRITTENDEN (APA-77) - After Able
Shows the 350 lb., aerial depth bomb, AN-Mk. 54, Mod. 1, HBX loaded and plugged after
it had been torn from its securing cable and blown 6 feet inboard by the blast. The
Tail Fin Assy. received extensive damage (beyond repair for personnel in the field)
and the preservative paint on the bomb casing was slightly scorched by the heat flash
of the "A" bomb. The original position of the bomb was on the Ol deck, frame 48,
stbd. side.
Photo. No. AA-CR-60-145-7.

#### SECRET



U.S.S. CRITTENDEN (APA-77) - After Able
Shows the final position of the 500 lb., general purpose, aircraft bomb, AN-M64Al,
TNT loaded and plugged, after it had been blown 12 feet aft and 7.2 feet inboard by
the blast. The original position of the bomb was on the 01 deck, frame 42, stbd. side.
The Tail Fin Assy. received negligible damage. Indications of excess temperatures
were not present.
Photo. No. AA-CR-98-1960-1.

#### SECRET



U.S.S. BARROW (AFA-61) - Before Able Shows the 5".0 Aircraft hocket Heads, plaster loaded and fuzed, in position prior to Test "A". The stowage of Rocket Heads as shown in this view was employed for all Special Test Rocket Heads of this type. Photo. No. BA-CR-93-128-1.

### SECRLI

March and a second


Enclosure (D) to Director Ship Material Serial 001500.

Page 179 of 249 pages. Volume III.



U.S.S. BUTTL, (APA-68) - Before Able Shows the Incendiary Bomb Clusters, AN-E12, in position for Test "A". The Clusters were located in the forward troop ammunition hold. Photo. No. BA-CR-93-128-3.

### SECHET



U.S.S. GASCONAIR (AFA-85) - Before Able Shows the Incerciary homb Clusters, AN-M12 in position for Yest "A". The Clusters were located in compartment C-201-L. This location was selected for test purposes in order not to endanger instruments located in other parts of the vessel. Photo. No. FA-Ch-93-128-5.

### SEGEET

knolesure (D) to Director Ship Material Cerial 201500.


Page 181 of 249 pages. Volume III.



U.S.S. GASCONADE (APA-85) - Before Able Shows the 5"/38 projectile stowage C-305-M. Photo. No. BA-CR-81-432-11.

Enclosure (D) to Director Ship Material Serial 001500.

Page 182 of 249 pages. Volume III.




U.S.S. GARCONADE (APA-85) - Before Able Shows the 5"/38 powder magazine C-306-M. Photo. No. BA-CR-81-432-12.

## SECHET



U.S.S. CASCONADE (APA-85) - Before Able Shows the 40 MM Clipping Room A-0104-M. Photo. No. BA-CR-81-433-3.

# SEVEET



U.S.S. GASCONDADE (APA-85) - After Baker Shows the effect of shock to the 5"/38 projectile stowage in magazine, C-305-M. The failure of battens and stanchions was marked. Photo. No. AB-CR-100-4207-1.



U.S.S. GASCONADE (APA-85) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage in the Ready Service Room, C-0104-M. The failure of battens and stanchions was marked.

Photo. No. AB-CR-100-4207-3.



U.S.S. GASCONADE (APA-65) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage in the Ready Service Room, C-0101-M. The failure of battens and stanchions was marked.


Photo. No. AB-CR-100-4207-4.

### SECHLI




U.S.S. GASCONADE (APA-85) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage in Magazine, C-404-M. The failure of battens and stanchions was marked.

Photo. No. AB-CR-100-4207-5.




U.S.S. GASCONADE (APA-85) - After Baker Shows the effect of shock to the 5"/38 Projectile Stoage in Megezine, C-305-M. The failure of battens and stanchions was marked.

Photo. No. AB-CH-100-4210-11.



U.S.S. GASCONADE (APA-85) - After Baker Shows the effect of shock to the 5"/38 Powder Stowage in Magazine, C-306-M. The failure of battens and stanchions was marked.

Photo. No. AB-CR-100-4210-12.




Bhows the 350 lb., aerial depth tomb, AN-Mk. 54, Mod. 1, plaster loaded and fused with a AN-Mk. 219 nose fuse and a AN-Mk. 230 Hydrostatic Tail Fuse secured in position for Test "A". The method of securing the bomb to the deck is typical of all aviation munitions exposed on the toy sides of target vessels. The Lomb was located on the 01 deck, frame 32, port side.

Photo. No. BA-CH-76-129-6.


## SECRET

Enclosure (D) to Director Chip Naterial Ser 1 0 1,000.




U.S.S. CATHON (APA-71) - Before Able
Shows the 500 lb., general purpose, sircroft bomb, AN-M64Al, plaster loaded and fused
with a AN-M103 nose fuze and AN-M101A2 tail fuze in position for Test "A". The method
of securing the bomb to the deck is typical of all aircraft munitions exposed on the
top sides of target vessels. The bomb was located on the 01 deck, frame 32, stbd. sides
Photo. No. BA-CR-76-129-7.

SECSIZ



U.S.S. CATRON (APA-71) - Before able Shows the Jet Assisted Take-off Unit, 12AS1000b, potassium perchlorate, asphalt, and oil loaded, in position prior to Test "A". Photo. No. BA-CR-85-591-6.

Frandag



U.S.I. CATRON (AFA: '1) - before Able thows the Etern view 500 lb., general purpose, sircraft bomb, AN-M64Al, plaster loaded and fuzed with a AN-103 nose fuze and M-116 tail fuze. The method of securing the comb to the deck is typical of all aircraft munitions exposed of the top sides of turnet vessels. The bomb was located on the Ol deck, frame 32, stbd. side. Proto. No. DA-CR-85-591-9.

世界したり業



U.5.5. CATRON (APA-71) - Before Able Shows the 500 lb., general purpose, aircraft bomb, AN-M6/Al, plaster loaded and fused: AN-M103 Nose Fuse; AN-M 102A2 Tail Fuze, in position prior to Test "A". Photo. No. BA-CR-85-591-10.

### SECRET



U.D.S. CATRON (APA-71) - Before Able Shows the 350 lb., Aeriel Depth bomb, AN-MR. 54, Mod. 1, plaster loaded and fused: AN-MIO3Al Nose Fuze; AN-MR. 230-6 Hydrostatic Tail Fuse, in position prior to Test "A". Photo. No. BA-CR-85-591-12.

### LACELT



U.S.S. CATRON (APA-71) - Before Able Shows the 5".0 Aircraft Rocket Heads, plaster loaded and fuzed, in position prior to Test "A". Photo. No. BA-CK-85-592-1.

SECRET


Enclosure (D) to Director Ship Material Serial 001500.

Page 197 of 249 pages. Volume III.

ारः - कृष्टिकोत्तरभ्यक्तिरः अकल्पातिकोतः १५८८ अस्तिकेल्




U.b.s. BLADEN (APA-63) - Before Able
Shows the typical arrangement of the display of aircraft munitions and a floating
Mine employed in both tests "A" and "B" on APA's. Not the following: 350 lb.,
aerial depth bomb frame 32, port; Jet Assisted Take-off Unit, frame 45, port;
500 lb., general purpose, aircraft bomb, frame 32, atbd.,; Floating Mine, Mk. 6,
frame 34, atbd.
Photo. No. BA-CR-76-298-4.



U.S.S. BRISCON (APA-65) - Before Able Shows the 5".0 Aircraft Rocket Heads, plaster loaded and fuzed, in position prior to Test "A". Photo. No. PA-CR-97-422-7.



U.S.S. BRISCOE (APA-65) - Before Able Shows the 20 MM Clipping Room, B-0309-M prior to Test "A". Photo. No. BA-CR-97-422-8.




3 A.CR 97- 454

U.S.S. bRISCOE (APA-65) - Before Able Shows the 40 MM Ready Service Room, C-0104-N prior to Test "A". Photo. No. RA-CR-97-454-1.

SECHLT

Enclosure (D) to Director Ship Material Serial 001500.

Page 201 of 249 pages. Volume III.



U.S.S. BRISCOE (APA-65) - Before Able Shows the 40 MM Magazine, C-302-M prior to Test "A". Photo. No. BA-CR-97-454-5.



U.S.S. BRISCOL (APA-65) - After able Shows the 5".O Aircraft Rocket Heads after Test "A". The Rocket Heads were plaster loaded and fuzed and remained unharmed during Test "A". Photo. No. AA-CR-92-1776-1.



U.S.S. BRISCOE (APA-65) - After Eaker
Shows the effect of shock to the 20 MM Magazine Ready Service Stowage in the 20 MM Clipping Room, E-0109-M. A feasible securing device should be provided for the racks holding the loaded Magazines to prevent them from becoming disengaged when subjected to a violent upward movement.
Photo. No. AB-CR-97-4046-3.

### FFFFFF

Enclosure (I') to Director Ship Meterial Cerial OG1500.

Page 204 of 249 pages. Volume III.




U.S.S. BRISCOL (APA-65) - After Baker Shows the effect of shock to the 40 MM Ammunition Stowage in the 40 MM Ready Service Room, G-0104-M. The failure of batters and stanchions was marked. Photo. No. AB-CR-97-4046-4.

## SECRET

Enclosure (D) to Director Ship Material Serial 001500.

tage 205 of 249 pages. Volume III.




U.5.5. BANNER (APA-60) - Before Able Shows the 500 lb., general purpose, aircraft bomb, AN-M6/Al, TNT loaded and with shipping plugs in place, in position prior to Test "A". The securing arrangement to the deck as seen in the photo was employed for all aircraft munitions exposed on weather decks. Photo. No. BA-CR-85-353-9.

### ECKET

nelosure (D) to Director Ship Material Serial 001500.

hage 206 of 249 pages. Volume III.




U.S.S. BANNER (APA-60) - Fefore Able Shows the 350 lb., Aerial Depth Bomb, AN-Mk. 54, Wodl, HBN joaded and with shipping plugs in place, in position prior to Test "A". The securing arrangement as seen in the photo was employed for all Aircraft Munitions exposed on weather decks. Photo. No. BA-CR-85-353-10.

ELLBER


Enclosure (b) to Director Ship Material Serial 001500.

Page 207 of 249 pages. Volume III.




U.S.S. FALLON (APA-S1) - Before Able Shows the 5"/38 Ready Service Powder Box and its condition of readiness prior to Test "A". Photo. No. BA-CR-60-515-10.


## LECKET



U.S.S. FALLON (APA-81) - Before Able Shows the 5"/38 Powder Stowage in the Ready Service Box prior to Test "A". Photo. No. BA-CR-60-515-11.



U.S.S. FALLON (APA-81) - Before Able Shows the condition of readiness of the 5"/38 Ready Service Boxes prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-60-515-12.




U.D.S. FALLON (APA-81) - Before Able Shows the 5"/38 Projectile Stowage in the Ready Service boxes prior to Test "A". All ammunition is Service Ammunition. Photo. No. FA-CR-60-516-1.

# FFCFFT.




U.S.S. FALLON (APA-61) - Before Able Shows the condition of readiness of the 20 LM Ready Service Box prior to Test "A". Ammunition stowed within is Service Ammunition. Photo. No. BA-CR-60-516-2.

### BECFFI




U.S.S. FALLON (APA-81) - Hefore Able Shows the method of stowing 20 MM Ammunition, in boxes, in the Reedy Service Boxes prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-Ch-60-516-3.

### SECKET



U.S.S. FALLON (APA-81) - Before Able Shows the 40 MM Ammunition Stowage in Magazine, A-404-M prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-60-917-9.




U.S.S. FALLON (APA-81) - Before Able Shows the Pyrotechnic Ammunition Stowage in the Pyrotechnic Locker prior to Test \*A\*. Munitions as shown is Service Ammunition. Photo. No. BA-CR-60-917-10.

#### SECELT




U.S.S. FALLON (APA-81) - Before Able Shows the condition of readiness of the Pyrotechnic Locker prior to Test "A". Service Pyrotechnic Munitions were employed in the Test. Photo. No. BA-CR-60-917-11.



U.S.S. FALLON (APA-81) - Before Able Shows the 40 MM Ammunition Stowage in the Rendy Service Room, C-0104-M prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-60-918-1.


SECHET



U.S.S. FALLON (APA-S1) - Before Able Shows the 40 MM and Smell Arms Ammunition Stowage in Magazine, C-302-M prior to Test "A". All Ammunition is Service Ammunition. Photo. No. BA-CR-60-918-2.

#### SECHEI





U.S.S. FALLON (APA-81) - Before Able Shows the 5"/38 Powder Stowage in Magazine, C-306-M, prior to Test "A". Photo. No. BA-CR-60-918-4.

SECHLI



U.S.S. FALLON (AFA-81) - Before Able Shows the 5"/38 Projectile Stowage in Magazine, C-305-M, prior to Test "A". All ammunition is Service Ammunition. Photo. No. BA-CR-60-918-5.

#### SICHET



U.S.S. FALLON (APA-81) - before Alle Shows the 5"/38 Projectile blowage in Magazine, C-305-M prior to Test "A". All projectiles are Service Ammunition. Photo. No. EA-Ch-60-918-6.



U.C.S. FALLON (APA-81) - After Able Shows the blast damage incurred to the 5"/38 Ready Service Locker and 5"/38 Powder Tanks. The Powder Tanks in position parallel to the edge of the doors were indented, how ver, withdrawal of the Cartridged Cases revealed no damage. Surveillance test of the smokeless powder exhibited no signs of damage or deterioration. Photo. No. AA-CR-87-2540-1.

#### 5 4 6 h 4 T




U.S.S. FALLON (APA-81) - After Able Shows the blast damage incurred to the 5"/38 Keady Service Locker and 5"/38 Powder Tanks. The Fowder Tanks in position parallel to the edge of the doors were indente however, withdrawal of the Cartridge Cases revealed no damage. Surveillance Test of the smokeless powder exhibited no signs of damage or detrioration. Photo. No. AA-CR-87-2540-2.

#### SECELT




U.D.S. FALLON (APA-81) - After Baker Shows the effect of shock on the 40 MM Ammunition Stowage in the Main Dock Clipping Room, C-0104-M. Failure of bettens and retaining stanchions was marked. Photo. No. AB-Ch-62-4166-7.

# FFCFFI




U.S.S. FALLON (APA-81) - After Baker
Shows the effect of shock on the 20 MM Ammunition Ready Service Box. This box was
filled to its capacity but was improperly closed. The upward motion of the ship was
great enough to force the lid open and toss several cases of 20 MM Ammunition about th
deck as can be observed in the photo.
Photo. No. AB-CR-64-4166-9.




U.S.S. FALLON (APA-81) - After Baker
Shows the effect of shock on the 20 MM Ammunition Ready Service Box. The sudden upward
movement of the ship was of such magnitude that the deck fittings of the Ready Service
pow failed to remain fast. The Ready Service Box was filled to its capacity with boxed
30 MM Ammunition; this is promulgated to furnish an estimated gross weight. Dented case
of ammunition that was spilled from the Ready Service Box may be seen in the foreground.
Thoto. No. AB-CR-62-4166-11.

#### RECRET



U.S.S. GILLIAM (APA-57) - Before Able Shows the exposed 40 MM Ammunition in the bulwark shields on display for Test "A". Photo. No. BA-CR-81-561-11.




U.S.S. LST-133 - Before Able Shows the Small Arms Stowege in Magazine, A-3102-M, prior to Test "A". Photo. No. BA-CR-234-381-11.

ELCRET

anclosure (D) to Lirector Ship Material Serial 001500.

Page 228 of 249 pages. Volume III.

4214




U.S.S. IMP-133 - Before Alle Shows the Pyrotechnic fitmers in the Fyrotechnic Locker prior to Test "A". The hyrotechnic literage as shown in this view is a typical storage on impte. Photo. No. Ea-Ch-234-381-17.

# SECPLT

Enclosure (L) to Director Ship Material manual of 16 m.

Page 229 of 249 pages. Folume III.



U.S.S. LST-133 - After Able Shows the 20 MM Ammunition Ready Service Locker in position prior to Test "E". Photo. No. AA-CR-234-381-7.



U.S.S. IST-133 - After Able
Shows the loaded 20 MM Magazines in position in the
Ready Service Box prior to Test "B".
Photo. No. AA-CR-234-1381-8.

# BECRET



U.S.S. IST-133 - After Beker Shows the extent of damage to the 20 MM Ammunition Ready Service Box and 20 MM loaded magazines from the cascading column of water. Photo. No. AB-CR-82-4218-4.

# SECHET




U.S.S. LST-133 - After Baker Shows the extent of damage to the 20 MM Ammunition Ready Service Box and 20 MM loaded magazines from the cascading column of water. Photo. No. AB-CR-82-4218-5.

#### SECHET



U.S.S. LET-133 - After Baker Shows the extent of damage to the 20 MM Ammunition Ready Service Box and loaded magazines from the cascading column water. Photo. No. AB-CR-82-4218-6.

# SECEET




U.S.S. LST-133 - After Baker Shows the blast damage to the 20 MM Reddy Service Hox. The loaded magazines inside the Box were not damaged. Photo. No. AB-CR-82-4218-7.

SESBLI



U.S.S. IST-133 - After Baker Shows the condition of the 20 MM Ammunition Ready Service Box after it had been subjected to blast from the Atom Bomb. Photo. No. AB-CR-87-4218-8.

# SECHLI




U.S.D. LET-545 - Before Able Shows the 40 : M Amminition Stowage prior to Test "A". The Stowage as shown in thi: view is typical for LET's. Photo. No. DA-CR-92-931-1.

BLUBLT

Enclosure (D) to Director Ship Material Serial 001500.

iage 237 of 249 pages. Volume III.




U.S.S. IST-545 - Before Able Shows a typical 20 MM Ammunition Stowage in the IST type magazine prior to Test "A". Photo. No. BA-UR-92-931-3.

#### SECRLI

Enclosure (D) to Director Ship Material Cortal Colt No.

Page 238 of 249 pages. Volume III.




U.C.J. INTERS - person Relationship in the Remay Shows the 20 MM Annual Union of the in the Remay Service how prior to leet "a".

Photo. No. DA-C:-9a-9gl-4.

#### SELLLIT

Buclomme (b) to Dir abor Dhy Returiel herisk 201900.




U.S.S. LST-5A5 - Before Able Shows the 4".5 Rocket Head, White Phosphorous loaded, Stowage in the 20 MM Ammunition Ready Service Box prior to Test "A". Photo. No. BA-CR-76-941-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 240 of 240 pages. Volume III.



U.S.S. LET-220 - Refore Able Shows the 4".5 Rocket Head Stowage, white phosphorous loaded, in the stbd. 40 MM Ready Service Locker located on the stern, prior to Test "A". Photo. No. BA-CR-81-975-7.



U.S.S. LCI-615 - Before Able Shows the Pyrotechnic Stowage in the Pyrotechnic Locker. Photo. No. BA-CR-234-380-10.




U.S.S. IC1-615 - Pefore Able Shows the Small Arms Stowage in the ICT type magazine. Photo. No. BA-CR-234-380-11.

SECEET


Enclosure (I) to Director Ship Material Serial 001500.

Page 243 of 249 pages. Volume III.




U.S.S. ICI (L)-327 - Before Able Shows the loaded 20 MM Magazine in position in the Ready Service Box. Photo. No. BA-CR-93-982-2.


#### SECRET



U.S.S. ICI-620 - Before Able Shows the loaded 20 MM Magazine Ready Service Stowage on board an ICI. Photo. No. BA-CR-234-381-3.



U.S.S. SALT LAKE CITY (CA-25) - Before Able Shows the Special Guided Missle, (STV), in position prior to Test "A". Photo. No. BA-CR-92-901-11.



U.S.S. SALT LAKE CITY (CA-25) - after Able Shows the Special (mided Missle located on the main deck. No damage was inflicted from the "A" bomb. Photo. No. AA-CR-60-136-7.

SECLET

Enclosure (D) to Director Ship Material Social 001500.

Page 247 of 249 pages. Volume III.



U.S.S. SALT LAKE CITY (CA-25) - After Able Shows the Special Guided Missle, (STV), after Test "A" and that it had remained unharmed. Pre-Test "A" picture, RA-CK-92-901-11 may be employed for comparison. Photo. No. AA-CK-87-2539-11.



U.S.S. BRUIL (AFA-66) - After Able Shows the crated Special Guided Missle, (STV) after Test "A". The Missle remained unharmed. Photo. No. AA-CR-87-2539-10.



#### Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 🕈	XRD-203-Section 12 ✓
AD-366589	XRD-200-Section 9
AD-366590 -	XRD-204-Section 13
AD-366591►	XRD-183
<b>∠</b> AD-366586 <b>★</b>	XRD-201-Section 10
∠AD-367487. <b>以</b>	XRD-131-Volume 2-
✓AD-367516¥	XRD- <b>₹</b> 143 ►
✓AD-367493 <b>८</b>	XRD-142 -
AD-801410L ✔	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 <b>✓</b>
✓AD-376828L 🍟	XRD-76/
✓AD-367464. <b>※</b>	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100✓

# Subject: Declassification of Reports

Declassification of	Reports	
✓AD-367491 🔾	XRD-134-Volume	2 -
✓AD-367479 <b>\</b>	XRD-123 /	
✓ AD-367478 <b>火</b>	XRD-122 ✓	
✓AD-367481 💢	XRD-125 ✓	
AD−367500 <b>V</b> .	XRD-159-Volume	2 rainges
AD-367499 💢	XRD-160-Volume	3 <b>~</b>
AD-367498 🖈	XRD-161-Volume	4 -
AD-367512 🗸	XRD-147	
AD-367511 🗸	XRD-148	
AD-367465 🔻	XRD-107 ►	
AD-366733 ✔	XRD-43	
AD-367477 🗡	XRD-121 ✔	
AD-367476 👫	XRD-120 <b>☞</b>	
AD-367467 💢	XRD-109-Volume	1
AD-367475 💸	XRD-119 ✓	
AD-367474 🔥	XRD-118	
AD-367473 🔥	XRD-117 ✓	
AD-367472 🕏	XRD-116 ✓	
AD-367471 🖈	XRD-115 <b>✓</b>	
AD-367466 🖟	XRD-108 ✓	
AD-801405L 🗸	XRD-113	
AD-367470 💸	XRD-112*	
AD-367469 🚶	XRD-111 ✔	

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center